

Operation Experience with SNS RFQs

Sang-ho Kim, SNS/ORNL On behalf of the SNS team

Presented at: 'High Intensity RFQ meets Reality' Workshop Heidelberg, Germany

April 15-16, 2019

ORNL is managed by UT-Battelle, LLC for the US Department of Energy



Acknowledgement

- The materials presented are collection of tremendous efforts from a large number of people at SNS/ORNL.
- The people at SNS who contributed to SNS RFQ efforts include A. Aleksandrov, W. Barnett, M. Champion, S. Cousineau, M. Crofford, G. Dodson, J. Galambos, N. Gerber, S. Henderson, G. Johns, Y. Kang, A. Menshov, R. Morton, S. Murray, S-W. Lee, C. Luck, R. Peglow, J. Pelfrey, C. Peters, F. Pilat, J. Price, T. Roseberry, A. Shishlo, M. Stockli, R. Welton, D. Williams, and many others

Outline

- SNS accelerator complex
- SNS operation history and status
- Experience with the original RFQ
- Experience with the new RFQ
- Summary





SNS operation history and status



CAK RIDGE SPALLATION NEUTRON SOURCE

SNS operation history and status



SNS Front-End (FE)

- FE System
 - 7.5-m long
 - H- ion source: 65 kV
 - Low energy beam transport system (LEBT)
 - 4-vane 402.5-MHz RFQ: 2.5 MeV
 - Medium energy beam transport system (MEBT)
- FE beam parameters
 - 26-mA macro-pulse average
 - 38-mA peak current
 - 70% beam-on chopping
 - 6% duty factor: 1 ms at 60 Hz







The original SNS RFQ (I)

- RF frequency: 402.5 MHz
- Design beam transmission: 90%
- Peak surface field: 83 kV (1.85 Kilpatrick)
- Dipole mode suppression: π-mode stabilizers
- Four segments: 3.7-m long
- RF power couplers: 8 coaxial couplers (later 2 coaxial couplers)
- Field profile tuning: 80 fixed slug tuners
- Vacuum pumping: Six cryopumps



The original SNS RFQ (I)

- RF frequency: 402.5 MHz
- Design beam transmission: 90%
- Peak surface field: 83 kV (1.85 Kilpatrick)
- Dipole mode suppression: π-mode stabilizers
- Four segments: 3.7-m long
- RF power couplers: 8 coaxial couplers (later 2 coaxial couplers)
- Field profile tuning: 80 fixed slug tuners
- Vacuum pumping: Six cryopumps





The original SNS RFQ (II)

- Resonance control: water temperature (two chillers: one for vanes and one for walls)
- Vane tip sensitivity: 40 MHz/mm
- -33 kHz/°C vane cooling water temperature
- +27 kHz/ °C wall cooling water temperature
- Glidcop/OFC braze joints





Issue (1) with the original SNS RFQ – Sudden detuning

- First detuning event in 2003
 - About -450 kHz detuning
 - Suspect Glidcop/OFC brazing joint but inconclusive
 - Happened when cooling water system control was down
 - Retuned and back to service
- Second detuning event in 2009
 - About -230 kHz detuning

Actional Laboratory

- Suspect Glidcop/OFC brazing joint but inconclusive
 - Happened when cooling channel was over-pressurized by accident
- Retuned and back to service



Issue (2) with the original SNS RFQ – Operational instability

- Difficult to keep RFQ in closed-loop as we increased duty factor (2009)
- Findings
 - Changes in net RF power while running at constant setpoints (field setpoint, cooling, etc.)
 - Net RF power=Forward pwr reflected pwr
 - Non-quadratic relation between net RF power and RFQ field amplitude
 - Correlation with Ion source/beam
- The root cause is not fully understood
 - Additional load (discharge somewhere in the structure?)



Operational improvement with the original SNS RFQ for > 1-MW operation (2009-2010)

- Reduced field setpoint
 - Kept 85%~90% beam transmission
- Reduced hydrogen flow in ion source
- Upgraded Chillers for cooling
- Improved vacuum pumping for ion source
- Implemented RF pulse length adjustment in LLRF control
 - About +/- 50 us RF pulse length



Actional Laboratory

Issue (3) with the original SNS RFQ – Beam transmission

- Gradual field profile changes
 - Happened over 2 years
 - Gradual (?) reduction of beam transmission by 20-30%
- No significant detuning
- Measured field flatness in 2013: -15/+5% (upstream/downstream)
 - Retuned in 2013

OAK RIDGE

- But beam transmission did not recover. Root cause unknown
 - Retuning is only for overall field balancing
 - If damages are around vanes, irreversible



The original SNS RFQ is marginally operable for1.4-MW beam power

New SNS RFQ (I)

- Same beam dynamics design
- Same RF input (2 coaxial couplers)
- Same resonance control scheme
- Design changes
 - Solid copper RF structure (vs. Glidcop/OFC brazing)
 - Improved vacuum pumping
 4 cryo-pumps and 4 turbo pumps
 - Improved water cooling
 - 4 rods for dipole stabilizer
 (vs. π-mode stabilizers)
 - RF seal scheme



New SNS RFQ (II)

- The new SNS RFQ was commissioned with beam at SNS beam test facility in 2017
- Installed for operation in 2018
- Performance

CAK RIDGE

National Laboratory

- Transmission: ~90% or higher
 - Provided a very stable beam for 1.4-MW operation with enough margin
- Beam emittances are satisfactory
- No non-quadratic growth of RF power with field



SNS front-end with the new RFQ demonstrated beam current required for PPU

- SNS Proton Power Upgrade (PPU) project: 2.8-MW capable accelerator
 - Increase beam energy: 1 GeV →
 1.3 GeV
 - Increase beam current (macropulse average): 26 mA → 38 mA
- Beam current out of new RFQ
 - > 40 mA macro-pulse average (>50 mA peak current)





Issue with the new SNS RFQ – RF seal (C-seal)

- RFQ tripped and required investigating
 - Happened at the end of the first period of FY19 machine run (Nov. 2018)
 - The new SNS RFQ had been operated at high power and high duty factor (>5%) for 4900 hours until this trip
- Findings
 - No quadrupole mode near the operating frequency, 402.5 MHz
 - A broken piece of the C-seal shorten two vanes at the downstream side
 - Damage of C-seal at both ends (more severe damage at the down stream side)



Damages









Octagonal-shape C-seal



C-seal failure

- Pure thermal load from surface RF field can not explain the RF seal failure
 - Total RF power loss on C-seal < 0.2 W (silver, copper)
- Investigation is ongoing for root cause
 - Bad contact?
 - Discharge? Multipacting?









AK RIDGE SPALLATION

National Laboratory

Temporary repair and back to operation

- No fundamental fix yet
 - Removed the broken C-seal piece
 - Cleaned damaged areas
 - Chemical cleaning for Ag and mild mechanical polishing
- RFQ back to service in Jan. 2019 and supported 1.4-MW operation for 2.5 months until planned machine outage
- Opened both ends of RFQ for inspection and repair
 - Severe damages of C-seal at the downstream end







Plans

- Task force has been formed for RFQ recovery
- Short/medium term
 - Replace RF-seal during planned outage period
 - Run RFQ at minimum field required for 1.4 MW
 - Design new RF seal and/or modify design for end plate
 - Test of new RF seal and/or modified design of end plate
- Long term Another new RFQ
 - No design changes except end wall/RF contact





Summary

- The issues experienced with the original SNS RFQ were not fully understood, however
 - RF truncations (faults)/trip rate increases with beam at higher duty factor
 - Sufficient (not marginal) cooling and vacuum pumping are essential
 - Non quadratic relation between net RF power and RFQ field is not understood. Suspect discharge
- The new SNS RFQ showed very good performances (high transmission, provided enough margin for 1.4-MW operation)
 - One critical design flaw is identified so far related to RF seal
 - It seems very problematic when RF seal is directly facing RF field
 - RF seal compression for good RF contact may not be enough
- Nuisances are design dependent
 - Unexpected issues can arise from innocuous design choices

Backup slide



Examples of the original SNS RFQ: Net RF power vs. Resonance error



CAK RIDGE National Laboratory

FY19 SNS Operating Schedule

SNS FY 2019 Q1-3 Official (02-28-19) SNS FY 2019 Q4 Unofficial (02-28-19)														·28-19)													
OutagesFY19A														FY19B					-		FY19C						
Oct-201	8	Nov-2018		Dec-2018		Jan-2	2019		Fe	b-2019		Mar	-2019		Арг	r-2019		May-2019		Jun-2019		Jul-2	019		Aug-2019		Sep-2019
1	1		1		1			1			1			1			1		1		1			1		1	
2	2		2		2			2			2			2			2		2		2			2		2	
3	3		3		3			3			3			3			3		3		3			3		3	
4	4		4		4			4			4			4			4		4		4			4		4	
5	5		5		5			5			5			5			5		5		5			5		5	
6	6		6		6			6			6			6			6		6		6			6		6	
7	7		7		7			7			7			- 7			7		7		7			7		7	
8	8		8		8			8			8			8			8		8		8			8		8	
9	9		9		9		//	9			9			9			9		9		9			9		9	
10	10		10		10			10			10			10			10		10		10			10		10	
11	11		11		11			11			11			11			11		11		11			11		11	
12	12		12		12			12			12			12			12		12		12			12		12	
13	13		13		13			13			13			13			13		13		13			13		13	
14	14		14		14			14			14			14			14		14		14			14		14	
15	15		15		15			15			15			15			15		15		15			15		15	
16	16		16		16			16			16			16			16		16		16			16		16	
17	17		17		17			17			17			17			17		17		17			17		17	
18	18		18		18			18			18			18			18		18		18			18		18	
19	19		19		19			19			19			19			19		19		19			19		19	
20	20		20		20			20			20			20			20		20		20			20		20	
21	21		21		21			21			21			21			21		21		21			21		21	
22	22		22		22			22			22			22			22		22		22			22		22	
23	23		23		23			23			23			23			23		23		23			23		23	
24	24		24		24			24			24			24			24		24		24			24		24	
25	25		25		25			25			25			25			25		25		25			25		25	
26	26		26		26			26			26			26			26		26		26			26		26	
27	27		27		27			27			27			27			27		27		27			27		27	
28	28		28		28			28			28			28			28		28		28			28		28	
29	29		29		29						29			29			29		29		29			29		29	
30	30		30		30			1			30			30			30		30		30			30		30	
31			31		31			1			31						31				31			31			
Oct-201	8	Nov-2018		Dec-2018		Jan-2	2019		Fe	b-2019		Mar	2019	1 1	Apr	-2019		May-2019	1	Jun-2019		Jul-2	019		Aug-2019	Г	Sep-2019
Acc	Accelerator Physics													Planned Machine Downtime (Maintenance/Upgrades)													
Acc	elerato	r Startun/R	lest	ore						Trane	ition	to No	utron	Pro	ducti	ion		Major Un	alanr	ed Outage	s (h	ackaro	unde		r is original	Inlar	
Acc	elerato	r Physice/	Mair	ntenance P	erio	de				mans					auct			Planned M	lach	ine Downti	me (Tunnel		sed	for Equipr	nent	Tests)
Sche	eduled	Maintenan	ce (starts at 06	6:30)												annean	aon	ine bowing		anne	0.010	500	. or Equip		10010)

CAK RIDGE National Laboratory