

# KOrea Multi-Purpose Accelerator Complex

- About KOMAC
- Operation Status
- Trouble-shooting
- > Plan
- Summary



#### **Facilities**





Bird eye view in June 2014


#### **Linac and Beam Lines**



#### Features of KOMAC 100MeV linac

- 50 keV Injector (Ion source + LEBT)
- 3 MeV RFQ (4-vane type)
- 20 & 100 MeV DTL
- RF Frequency : 350MHz
- Beam Extractions at 20 or 100 MeV
- 5 Beamlines for 20 MeV & 100 MeV

Output Energy (MeV)	20	100
Max. Peak Beam Current (mA)	1 ~ 20	1 ~ 20
Max. Beam Duty (%)	24	8
Avg. Beam Current (mA)	0.1 ~ 4.8	0.1 ~ 1.6
Pulse Length (ms)	0.1 ~ 2	0.1 ~ 1.33
Max. Repetition Rate (Hz)	120	60
Max. Avg. Beam Power (kW)	96	160



# **Control Room & Operator**



- EPICS based control system
  - Accelerator / Utilities / PSIS / RMS are controlled in the main control room
- Operators: 2 for accelerator, 2 for beam service in target room






## **Operation** (July 2013 ~ Sep. 2014)




- Operation plan : Weekly based
- Beam service : Monday ~ Friday
- Operation statistics (accumulated)
  - Operation: 4,092 hours (FY 2013: 2,290 hours / FY 2014: 1,802 hours)
  - Beam service: 879.2 hours (FY 2013: 432.7 hours / FY 2014: 446.5 hours)
  - Availability: FY 2013: 82.0%, FY 2014: 92.6 %




# Beam Service Statistics (2013~2014)



Total number of charges: 1,894 (2013: 937 charges / 2014: 957 charges)






Users in R&D fields




## Commissioning in 2014



- Goal : 10 kW beam @ 100 MeV
- Achieved 10 kW beam in August 2014
  - : 550us, 10Hz
- Normal operation with 10 kW is to start with revision of operation license





#### **Downtime Statistics at 2013**








Ion source 7%

DTL / RF 40%





- Moulator IGBT blast
- MPS interlock
- Moulator controller malfunction
- Klystron magnet fault
- Moulator Oil pump failure
- HV fault at Ion source
- LLRF controller fault
- RF arcing at Power coupler
- Electrical failure
- Shielding door failure
- PSIS PLC fault

## **Accelerator Downtime**



#### Utility

- Equipment wet at klystron gallery
- Cooling pump shut down
- Radiation shielding door failure

#### Modulator

- IGBT blasting
- Controller failure
- SCR firing circuit failure
- Oil pump failure

#### O DTL/RF

- RF arcing at a power coupler
- RF arcing at a slug tuner of DTL tank
- Dividing resistor failure for klystron

#### Ion source

- Solenoid failure
- High voltage switch failure
- Electro-magnetic power supply failure



## Issue: Utilities(1)



- Although completed commissioning of the utility, several troubles
- Long-term
  - Watered electronics in klystron gallery
  - : Due to unexpected triggering the fire extinguisher
  - : Shut down vacuum, RF and control system



Klystron gallery

**Klystron** 

Vacuum system



## Issue: Utilities(2)




#### Short-term

- Abnormal stopping cooling pump caused by momentary electrical power failure
- Tripped off vacuum system due to improper grounding
- Burned LEBT solenoid magnet by malfunction of cooling skid
- Waste in the strainer

: cooling system keeping the temperature of utility

: cooling unit of modulator







# Issue: Linac(1)



- Long-term
  - RF arcing during conditioning of DTL105
    - : frequent full reflections
    - : Forward RF power reached up to 800 kW (300 us, 2Hz) for a while
    - : After that, RF power was fully reflected and never recovered even under 80 kW



**During installation** 



**Back of Iris plate after arcing** 



Front of ridge loaded waveguide



Canted coil RF seal with indium sheet (0.3 mm) to fill the gap





# Issue: Linac(2)



#### Long-term

- RF arcing at a slug tuner of DTL tank
  - : when is increasing the pulse width and repetition
    - (1.2ms, 10Hz @ ~ 1 MW of forward power)
  - : broken vacuum due to burn the O-ring and then added the RF seal
- Short-term
  - RCCS control and klystrons failure
  - Flow-meter failure for DT 's electro-magnet





## **Issue: Modulator**


#### Long-term

- IGBT blasting at low duty 500us, 2Hz
  - : acted the fire detector and actuated CO2 gas
  - : cleaned the blasting debris on switching plate of A phase
  - : replaced IGBT's, IGBT drive boards
- Controller failure
- SCR firing circuit failure
- Short-term
  - IGBT over-current set value
  - SCR control circuit jumper

Oil pump hose and so on



#### Fire detector



## **Issue: Ion Source**



#### Long-term

- HV switch malfunction by HV arcing
  - : It cannot be repaired due to molded type
  - : long delivery and lead time
  - : changed the HV switch made in domestic company
  - : Although faults in twice, repair time reduced







HV switch: 60kV, Dong-A Hitech., Korea



## **Reduction downtime (1)**



- MPS (Machine Protection System)
  - Minimize the damage
    - Add interlock related with MPSmodulator, magnet's P/S
- Spare parts
  - Preparation items of long lead time for emergency
    - A type of a wholeness body
      - : klystron, circulator, other RF components, power supplies
    - A type of a partial components
      - : modulator
- Reduction of repair time
  - transfer the devices made in domestic company if possible
    - : HV switch





# Reduction downtime (2)




Management of items and spare parts

: set up MIS (Management Information System) which can be known the details of item as check the QR code on machine





**Tablet PC** 






**Control rack of modulator** 

## Plan for Beam Power Upgrade







## **Summary**



- Operation
  - **2013**
  - : Successfully commissioned 100 MeV linac with 1 kW
  - : Licensed normal operation (Nuclear Safety and Security Commission of Korea)
  - : Started user beam service in July.
  - **2014**
  - : Increased beam power to 10 kW
  - : Continued user beam service with improved beam conditions
- Reduction downtime
  - Add the interlock to continue
  - Maintain the sufficient spare parts
  - Transfer the devices made in domestic company
  - Manage the amount and history of items, systematically
- 2014 Plan
  - Get the operation license for 10 kW
  - Operate 10 kW of beam power in normal





# Thank you

