

STT Activities in Jülich

H. Hadamek, V. Kozlov, R. Nellen, S. Orfanitski, N. Paul, J. Ritman, M. Roeder, T. Sefzick, J. Uehlemann, P. Voigtländer, P. Wintz, P. Wüstner and IKP, ZAT, ZEL at FZJ

STT @ COSY-TOF

- Test System for PANDA-STT
- Beam time in May 2009 (2w)
- Calibration
 talk by M. Roeder

PANDA - STT

- Design issues
- Straw material order status
- Straw production



	COSY-STT	PANDA-STT
Straw materials	same (most)	
Straw layers	close-packed	close-packed
Geometry	stack of planar double-layers	hexagon sectors of planar double-layers
Straw length	1050mm	1200mm
Straw number	2700	4200
Gas mixture	Ar / CO ₂ (10-20%)	Ar / CO ₂ (10-20%)
Gas pressure	p=1.25 bar	p=2.0 bar
Environment	in vacuum	in atmosphere
Readout	preamps + discr. + TDCs	new dedicated readout
Spatial resolution	σ _{rφ} ~ 150μm	σ _{rφ} ~ 150μm, σ _z ~ 2 mm



STT @ COSY

- STT was installed in COSY-TOF vacuum barrel in summer 2008
- Only single days with beam, no experiment beam time
- Vacuum operation of ~ 6 months
- Micro gas leaks showed up, probably at gas manifolds
 - not seen before in surrounding atmosphere after years
 - but after months in surrounding vacuum (by low humidity)
- Decision to develop new gas manifolds and replace all


Complete dismounting of STT necessary



New Gas Manifolds for COSY-STT

- Old design (glued PP-profiles) with micro leaks after months in vacuum
- New design: steel pipes (Ø=6mm, d=100μm)
 - 37 gram per double-layer of 204 straws
 - X/X₀ ~ 1.2% per double-layer (2 pipes for in-/outlet)
 - STT leakage at permeation level, measured: ~ 5 litre/day (Ar/CO₂ 10%)

gas pins (52×30) fixed by laser welding (FZJ-ZAT)







16-Jun-09, PANDA Meeting, Torino

Peter Wintz



STT @ COSY-TOF Upgrade (1)


- Decision for upgrade in Jan-09
- Next allocated beam time was in May-09
- Tough schedule
 - Dismount all 30 straw layers
 - Identify µ-leaks ➡ located at gas manifolds
 - Exchange by 30 new gas manifolds made of steel
 - Produced at ZAT-FZJ
 - Replace few single straws with broken wires
 - Mount STT in COSY-TOF vacuum tank, reduction to 26 layers

All done within 3 months



STT @ COSY-TOF Upgrade (2)

Upgraded STT mounted at the COSY-TOF front cap



V. Kozlov & S. Orfanitski in front of STT



Mounting the front cap with STT to the vacuum barrel





16-Jun-09, PANDA Meeting, Torino

Peter Wintz



First Beam Time in May 2009


- 2 weeks for p p p K∧ at 2.95 GeV/c
- First experiment beam time with STT
- STT with 26 layers (2700 straws)
 - operated inside COSY-TOF vacuum (at ~ 4×10⁻³ mbar)
 - one straw with broken wire after installation (16ch HV sector off)
- Operation settings:
 - Ar/CO₂(10%) at p=1.25 bar (absolute)
 - 1600 V
- Threshold tuning (×170) of ASD8 discriminators
- Stable operation of detector & readout
- Implementing new STT into the COSY-TOF tracking algorithm
- Data analysis has just started ..



STT Performance

Clean and same TDC spectra for all 2700 straws

- σ (t_{max}=115ns) ~ 1ns $\Rightarrow \sigma$ (r_{max}=5mm) ~ 50µm (incl. wire sag)
- confirms precise straw diameter definition by pressurized film tube
- global space-time calibration for all straws
 talk by Matthias Roeder






STT Gas Mixtures

- Ar/CO₂(10%) at p=1.25 bar in COSY-TOF vacuum
 - gas gain: A ~ 10-15 ×10⁴ and 1570-1600 V
 - Inear space time relation, less critical to gas variations
 - small aging measured for some straws operated with 10% CO₂
- Ar/CO₂(30%)
 - no aging observed for all straws operated with 30% CO₂
 - non-linear space-time relation, but same resolution (PAVIA simul.)
- PANDA-STT operated at p=2.0 bar
 - higher ionisation density >> higher spatial resolution close to wire
 - few 100 V higher voltage, 1800 (10% CO₂) 2200 V (30% CO₂)
- Gas exchange ~ 4× V_{STT} / day (open exhaust) ➡ 3300 litre/day @ PANDA
- STT leakage measured: ≤ 1 mbar / h → ~10 litre/day @ PANDA



PANDA-STT Layout



PANDA Straw Material Order Status

(**ok**)

Mylar film tube

- 1550mm length, ~28µm film thickness,
- aluminised inside & outside (light shielding)

End plugs


- old design (yellow) (ok)
- new design (purple) design (purple)

Contact springs


- Cu/Be (ok)
- gold plating afterwards (in process)

Crimp pins

(in process)











Crimp Pin Problem

Quality problems of copper pins ('08⇒'09)

- unexpected for a repeat order at same company
- improper cutting (1.00×0.10mm OD×ID)
- cleaning by electrolytic etching possible
- but imperfect, inner hole diameters, ..
- stopped now

Must find new production company, maybe

- new material (steel?)
- new design
- new mass production
- new crimping test



view at pins from top

F



Straw Production

New straw production during past months:

- 1200mm length
- unwired due to lacking crimp pins
 - check mechanical setup
 - check skewed layer setup
- to be mixed later with wired straws for tracking
- removal of single straws inside d-layer tested
 - weaker mylar films (2×windings) than before
 - similar mylar (winding) imperfections than before

... waiting for new crimp pins ...



