

# Linac Department

- Infrastructure:
  - work on roof (TU/EH) ongoing, one leak closed, seems there are others ...
  - construction waste falling from ceiling onto cavity A1
  - to be repaired after beam time
- Operation: ready for rf-conditioning
  - works on roof (TU/EH) ongoing, one leak closed, seems there are others ...
  - camera surveillance of leak installed
- QQ-chamber design: ongoing, fall back solution designed and pieces arrive on site
- HSI-RFQ: electrode fabrication ongoing, tank #2 - #9 finished, y(#10) finished
- UHV controls: all cabinets delivered except one
- FoS:
  - plating procedure and material definition & procurement ongoing
  - test bunker: partially vacated, shielding works start today
  - first dummy drift tubes delivered to galvanic workshop
  - production of FoS started (visit at VA-TEC last Thursday)

