

- *COVID-19 impact for the time being:*
 - *staff “separated” into two shifts to reduce office occupancy to one person:*
 1. *home office (available by email & phone)*
 2. *on-site*
 - *some delay in communication with DANFYSIK, EPS, NCM*
 - *some delay in preparation of FoS (reduction of staff inside bunker to ≤ 2)*
- **Alvarez 2.0 - FoS:**
 - finalization of coupling loop optimization
 - preparations at test stand for hprf-test on schedule
 - external Cu-plating of flanges
- **pulsed stripper:** installation / operation / de-installation worked fine

