
UNILAC

QQ Chamber:

- A: all pieces in house
- B: testing starts next week

HSI RFQ:

- RFQ fully dis-assembled
- electrodes #2-3 exchanged



- leak identified
- in-house fixing feasible



- FoS:
 - cavity production on track
 - drift tube & stem production on track



- delayed (undefined)
- mitigation under discussion













