ESR Status February 12, 2019



- ring components available as in December 2018
- electron cooler high voltage power supply under repair
 ⇒ aiming for start of dry run February 18, engineering run February 25
- ring commissioning during engineering run in spring 2019:
 test longer storage times (should be possible), electron cooling and ring rf
 test, measurement and model optimization of orbit and tune
 if longer storage times and electron cooling available:
 test, measurement and model optimization of chromaticity
 further tests of diagnostics

options: first test operation of new barrier bucket cavity
test of deceleration in synchrotron mode
extraction and beam transport towards CRYRING
recommissioning of stochastic cooling system