MM 18.09.2019 - PSU

Alvarez 2.0:

- MSP plan put on server
- started process of refining human resources for (de)installation & commissioning

FoS:

- SAT (repetition of FAT after transp.)
 - all ok, except ...
 - vacuum: Cu seals -> to be checked
- low level rf-measurements started
 - empty cavity: first modes measured as predicted
- today: transport of first drift tube & stem to GALVANO-T for Cu-plating

Safety

 List of "prüfpflichtige Arbeitsmittel" sent to M. Hirsch incl. potential issues -> awaiting response

