## **ESR Status** October 23, 2018



- new configuration of electron cooler SCUs resulted in ability to control and ramp those power converters
- reconfiguration of other power converters is going on
- some software subroutines are still incomplete (rf, pulsed septum)
- dry run is paused for modifications of power converters
- calibration of scrapers in the electron cooler completed