

- shutdown:
 - dismantling HSI-LEBT started
 - RFQ, SL, IH-1 vented
 - movements of tunnel sections observed
 - measure / re-align post-stripper
- QQ-chamber: procurement of parts ongoing
- HSI-RFQ: X-ray tests done, four hot spots identified
- UHV controls upgrade: on schedule
- FoS:
 - production of FoS mantle and end plates ongoing
 - DT-study tendered, offers due on May 2nd
 - undefined delay of dummy plating (dedicated meeting on May 16th)

