

Ion Source Status

April 02, 2019

- Ion source operation is performing very smoothly:
- $^{107}\text{Ag}^{3+}$ beam from VARIS@Terminal North; good intensity and stability
- PIG@Terminal South in standby for next beam run
- $^{48}\text{Ca}^{10+}$ beam from ECRIS@HLI, very stable high duty cycle operation